2004/03/16 14:50 2001/04/19 13:00 2001/04/19 13:02 2001/04/21 19:28 2001/04/19 13:06 2001/04/19 13:06 2001/04/19 13:07 2001/04/19 13:08
2001/04/19 13:02 2001/04/21 19:28 2001/04/19 13:06 2001/04/19 13:06 2001/04/19 13:07
2001/04/21 19:28 2001/04/19 13:06 2001/04/19 13:06 2001/04/19 13:07
2001/04/19 13:06 2001/04/19 13:06 2001/04/19 13:07
2001/04/19 13:06 2001/04/19 13:06 2001/04/19 13:07
2001/04/19 13:06
2001/04/19 13:06
2001/04/19 13:07
2001/04/19 13:08
2001/04/19 13:08
1
2001/04/19 13:09
2001/04/19 13:10
2001/04/10 12:10
2001/04/19 13:10
2001/04/19 13:14
2001/04/19 13:12
2001/04/19 13:12
2001/04/19 13:18
2001/04/19 13.18
2001/04/10 12 10
2001/04/19 13:18
2001/04/19 13:20
2001/04/19 13:19

	90494	(atoms to along storing posicity) and (achille line point) along	LICDAT.	2002/07/02 00:26
-	80484	(stress tension strain weigh) and (cable line wire).clm.	USPAT;	2002/07/02 09:36
			EPO; JPO; DERWENT;	
	10275	(// 4 4 2 2 2 1) 1 (- 11 - 12 2 - 2 - 2 1 - 2 2 2 - 2	IBM_TDB	2001/04/10 12 20
-	10275	((stress tension strain weigh) and (cable line wire).clm.) and measure	USPAT;	2001/04/19 13:20
			ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	
-	1025	((stress tension strain weigh) and (cable line wire).clm.) and	USPAT;	2001/04/19 13:20
		measure.clm.	ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	
-	122	(((stress tension strain weigh) and (cable line wire).clm.) and	USPAT;	2001/04/19 13:21
		measure.clm.) and (gage gauge).clm.	ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	
-	11	((((stress tension strain weigh) and (cable line wire).clm.) and	USPAT;	2001/04/19 13:21
		measure.clm.) and (gage gauge).clm.) and jack	ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
-	39113	(stress tension strain weigh) and (cable wire).clm.	USPAT;	2001/04/19 13:22
			ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	
_	18	((stress tension strain weigh) and (cable wire).clm.) and measure and	USPĀT;	2001/04/19 13:26
		jack and (gage gauge).clm.	ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
_	159546	wire near stain naear gauge	USPAT;	2001/04/19 13:27
	10,000	hard transfer burner	ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
1_	2	wire near stain near gauge	USPAT;	2001/04/19 13:27
		Wife field staff field gauge	ЕРО; ЈРО;	2001/01/15 15.27
			DERWENT;	
			IBM_TDB	
	5	(wire cord cable) near (stain force stress) near gauge	USPAT;	2001/04/19 13:38
-		(while cord caole) hear (stain force sitess) hear gauge	ЕРО; ЛРО;	2001/04/17 13.50
			DERWENT;	
			IBM_TDB	
	146	(wire cord cable) near4 (stain force stress) near4 gauge	USPAT;	2001/04/19 13:38
-	140	(who cord capic) heart (sain force sucss) heart gauge	ЕРО, ЛРО,	200110711713.30
			DERWENT;	
			IBM_TDB	
	109420	deflect(wire cord cable) near4 (stain force stress) near4 gauge	USPAT;	2001/04/19 13:59
-	107420	deficed wife cord caore) fical 4 (stain force suless) fical 4 gauge	ЕРО; ЛРО;	2001/04/17 13.37
			DERWENT;	
	21	((wire cord coble) nearl (ctain force stress) nearl covers) and (deflect	IBM_TDB USPAT;	2001/04/19 13:57
1-	21	((wire cord cable) near4 (stain force stress) near4 gauge) and (deflect	EPO; JPO;	2001/04/19 13:3/
1		deflection)	1 ' '	
			DERWENT;	
	_	((wire cord cable) near4 (stain force stress) near4 gauge) and (deflect	IBM_TDB	2001/04/10 12:57
-	9	, , , , , , , , , , , , , , , , , , , ,	USPAT;	2001/04/19 13:57
		deflection) and pull	EPO; JPO;	
			DERWENT;	
		1.0.4.16.4.16.4.11.2.11.2.11.2.11.2.11.2.11	IBM_TDB	2001/04/10 14 05
-	3	deflect and(wire cord cable) near4 (stain force stress) near4 (gauge	USPAT;	2001/04/19 14:02
		gage)and pull	EPO; JPO;	
			DERWENT;	
L	l		IBM_TDB	

-	856	deflect and(wire cable) and (stain force stress) and (measure\$4)and pull	USPAT; EPO; JPO;	2001/04/19 14:43
	ļ		DERWENT;	
			IBM_TDB	
-	3	deflect and(wire cable) near4 (stain force stress) near4 (measure\$4)and	USPAT;	2001/04/19 14:03
		pull	ЕРО; ЛРО;	
			DERWENT; IBM_TDB	
_	16	73/862.39\$.ccls. and pull and cable	USPAT	2001/04/19 14:15
_	82	73/862.451.ccls.	USPAT	2004/03/16 14:51
_	4	73/862.42.ccls. and pull and cable	USPAT	2001/04/19 14:24
_	205	deflect and(wire cable) and (stain force stress) and (measure\$4)and pull	USPAT;	2001/04/19 14:44
		and hydraulic	ЕРО; ЛРО;	
	ļ	·	DERWENT,	
			IBM_TDB	
-	38	deflect and(wire cable) and (stain force stress) and (measure\$4)and pull	USPAT;	2001/04/19 14:45
		and hydraulic .clm.	ЕРО; ЛРО;	
			DERWENT,	
]			IBM_TDB	
-	0	(deflect and(wire cable) and (stain force stress) and (measure\$4)and	USPAT;	2001/04/19 14:46
		pull and hydraulic) .clm.	EPO; JPO;	
			DERWENT; IBM_TDB	
	1	(deflect and(wire cable) and (stain force stress) and hydraulic) .clm.	USPAT;	2001/04/23 08:15
-	1	(deficet and whe capie) and (stain force suess) and nytratine) term.	ЕРО; ЛРО;	2001/04/25 08.15
			DERWENT;	
			IBM TDB	
-	6	73/862.391.ccls. and hydraulic	USPAT	2001/04/21 19:25
-	1	73/862.391.ccls. and (hydraulic).clm.	USPAT	2001/04/21 19:25
-	0	73/862\$3.ccls. and (measure and (stress tension strain) and cable and	USPAT	2001/04/23 08:46
		hydraulic and gage).clm.	i	
-	2	73/862\$3.ccls. and (measure and (stress tension strain) and hydraulic	USPAT	2001/04/21 19:29
		and gage).clm.		
-	1	73/\$6.ccls. and (measure and deflection and hydraulic and gage).clm.	USPAT	2001/04/23 11:52
-	538	(measure and deflection cable and hydraulic and gage).clm.	USPAT	2001/04/21 19:38
-	4	(measu\$4 and deflect\$4 and cable and hydraulic and (gauge gage)).clm. (measu\$4 and cable near4 deflect\$4 and hydraulic and (gauge gage))	USPAT USPAT	2001/04/21 19:32 2001/04/21 19:36
-	12	(tensiometer and cable near4 deflect\$4 and hydraulic and (gauge	USPAT	2001/04/21 13:50
-		gage)).clm.	OBIAI	2001/04/25 11:51
_	535		USPAT	2001/04/21 19:39
_	535		USPAT	2001/04/21 19:39
-	42		USPAT	2001/04/21 19:50
		(gage gauge)).clm.		
-	3	(Constitution of the contract	USPAT	2001/04/21 19:51
		jack and (gage gauge)).clm.		
-	34346	cable near4 (tension pull tes\$4)	USPAT;	2001/04/23 08:21
			ЕРО; ЈРО;	
			DERWENT;	
	3892	cable near4 (tension pull tes\$4).clm.	IBM_TDB USPAT;	2001/04/23 08:23
-	3892	cable hear4 (tension pun tes\$4).cm.	EPO; JPO;	2001/04/23 08.23
			DERWENT;	
			IBM_TDB	
_	1152	tensiometer	USPAT	2001/04/23 08:46
-	12	(tensiometer and cable).clm.	USPAT	2001/04/23 08:46
-	3	("4907458" "3839908" "4989450").pn.	USPAT	2001/04/23 11:52
-	5	proceq	USPAT	2001/11/02 15:55
-	2	wire near tension near meter	USPAT	2001/11/02 15:56
-	373	wire near tension and concrete	USPAT;	2001/11/02 16:30
			US-PGPUB;	
			EPO; JPO;	
			DERWENT;	
	<u> </u>	<u> </u>	IBM_TDB	L

-	68	wire near tension and concrete and hydraulic	USPAT; US-PGPUB;	2001/11/02 16:30
			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
_	68	(wire near tension) and concrete and hydraulic	USPAT;	2001/11/02 16:50
			US-PGPUB;	
			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
_	25	(wire near2 tension) and concrete and hydraulic and gauge	USPAT;	2001/11/02 16:51
		(Who hour tollion) and concrete and hy arabite and gauge	US-PGPUB;	2001/11/02 10:51
			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
_	108	73/862.42.ccls.	USPAT	2004/03/16 14:51
_	92	73/862.391.ccls.	USPAT	2001/11/05 13:08
_	82	73/862.381.ccls.	USPAT	2004/03/16 14:51
_	0	658118.URPN.	USPAT;	2001/11/05 13:30
		55513.0441.	US-PGPUB;	2001/11/03 13.30
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
	0	541850.URPN.	USPAT;	2001/11/05 13:30
_		341030.01414.	US-PGPUB;	2001/11/05 15.50
			EPO; JPO;	
			DERWENT;	
			IBM TDB	
1_	8	("2872808" "3679808" "3994162").PN.	USPAT;	2001/11/05 13:40
	0	2072000 3077000 3774102).114.	US-PGPUB;	2001/11/05 15.40
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
1_	1	5390550.URPN.	USPAT;	2001/11/05 13:40
-	1	3370350.OIQ 14.	US-PGPUB;	2001/11/05 15.40
			ЕРО, ЛРО;	
			DERWENT;	
			IBM TDB	
_	1	220668.URPN.	USPAT;	2001/11/05 14:18
		22000.01411.	US-PGPUB;	2001/11/03 14:10
,			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
_	0	73/144.ccls.	USPAT	2001/11/05 14:36
_	64	73/158.ccls.	USPAT	2004/03/16 14:51
_	178	73/144	USPAT	2001/11/05 16:13
-	3	4374473.URPN.	USPAT;	2001/11/05 14:39
			US-PGPUB;	
			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
_	1	4989450.URPN.	USPAT;	2001/11/05 14:43
		1707 1001.01111	US-PGPUB;	2501/11/05 14.45
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	0	D297818.URPN.	USPAT;	2001/11/05 14:48
_		527,010.ORI 14.	US-PGPUB;	2001/11/03 14.48
	1		ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
	J	<u> </u>	I IDIM_IDD	L

-	29	("D087988" "D271669" "D275087" "1780141" "2013810"	USPAT;	2001/11/05 14:48
		"3176510" "3410246" "3618379" "4163126" "4171640"	US-PGPUB,	
		"4534228").PN.	ЕРО; ЛРО;	
	t		DERWENT;	
			IBM_TDB	
	1	4125202 LIDDN		2001/11/05 14.56
-	1	4135393.URPN.	USPAT;	2001/11/05 14:56
			US-PGPUB;	
			ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	
-	17	("2245039" "2591724" "2723561" "3495454" "3512406").PN.	USPAT;	2001/11/05 15:04
			US-PGPUB;	
			ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	
<u>-</u>	2	3879999.URPN.	USPAT;	2001/11/05 15:04
	_		US-PGPUB;	2001/11/05 15:01
			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	*****
-	13	(tensiometer and (wire cable)).clm.	USPAT	2001/11/05 16:15
-	5317	((measur\$4 detect\$4 determin\$4 estimat\$4 sens\$4 meter\$4) and (stress	USPAT;	2002/07/02 09:41
	ŀ	tension strain weigh) and (cable line wire)).clm.	ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	
-	347	(((measur\$4 detect\$4 determin\$4 estimat\$4 sens\$4 meter\$4) and (stress	USPAT;	2002/07/02 09:45
		tension strain weigh) and (cable line wire)).clm.) and hydraul\$4.clm.	ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	
1_	41	((((measur\$4 detect\$4 determin\$4 estimat\$4 sens\$4 meter\$4) and	USPAT;	2002/07/02 13:49
	1	(stress tension strain weigh) and (cable line wire)).clm.) and	EPO; JPO;	
		hydraul\$4.clm.) and ((measur\$4 detect\$4 determin\$4 estimat\$4 sens\$4	DERWENT;	
		meter\$4) near4 (deflect\$4 deviat\$4 bend\$4))	IBM_TDB	
	0	73/144.ccls.	USPAT;	2002/07/02 13:49
-		73/144.0CIS.	1	2002/07/02 13.49
			EPO; JPO; DERWENT;	
			IBM_TDB	
	105	73/144	USPAT;	2002/07/02 13:50
1 -	185	73/144	,	2002/07/02 13.30
			ЕРО; ЛРО;	
			DERWENT;	
	1		IBM_TDB	
-	3	("3174334" "3653258").pn.	USPAT;	2002/07/02 13:51
			ЕРО; ЈРО;	
1			DERWENT;	
1			IBM_TDB	
-	3	("4333353" "5738097" "5406854").pn.	USPAT	2002/07/03 13:09
-	5	(hydrauli\$4 near4 (jack brac\$4 lever)) same ((wire cable strand rope	USPAT	2003/03/27 13:13
		rod) near4 (measur\$4 test\$4 meter\$4 determin\$4 sens\$4 detect\$4		
1		estimat\$4) near4 (deflect\$4 displac\$4 mov\$4 bend\$4))		
-	12		USPAT	2003/03/27 13:13
		rod) near4 (measur\$4 test\$4 meter\$4 determin\$4 sens\$4 detect\$4		
	1	estimat\$4) near4 (deflect\$4 force displac\$4 mov\$4 bend\$4))		
_	9	(hydrauli\$4 near4 (jack brac\$4 lever)) same ((wire cable strand rope	USPAT;	2003/03/27 13:17
1		rod) near4 (measur\$4 test\$4 meter\$4 determin\$4 sens\$4 detect\$4	US-PGPUB;	2003.03.27 13.17
		estimat\$4) near4 (deflect\$4 displac\$4 mov\$4 bend\$4))	EPO; JPO;	
		Commany mean (democrat displaces moves beindes))	DERWENT;	
1				
			IBM_TDB	2002/04/02 20 00
-	0	equation near4 calcualt\$4 near4 tension\$4 near4 deflect\$4	USPAT	2003/04/02 20:09
-	0	equation near4 calcualt\$4 near4 tension\$4	USPAT	2003/04/02 20:10
-	146	equation near4 calculat\$4 near4 tension\$4	USPAT	2003/04/02 20:10
-	6	equation near4 calculat\$4 near4 tension\$4 near4 (deflect\$4 bend\$4)	USPAT	2003/04/02 20:12
-	4	(equ\$5 near4 calculat\$4 near4 tension\$4 near4 (deflect\$4 bend\$4))	USPAT	2003/04/02 20:18
L	4	(force near4 calculat\$4 near4 tension\$4 near4 (deflect\$4 bend\$4))	USPAT	2003/04/02 20:18

Search History 3/18/04 11:46:50 AM Page 5

-	111	73/862.391.ccls.	USPAT	2004/03/16 15:06
-	92	73/862.451.ccls.	USPAT	2004/03/16 14:53
-	110	73/862.42.ccls.	USPAT	2004/03/16 16:51
-	109	73/862.381.ccls.	USPAT	2004/03/16 14:51
-	68	73/158.ccls.	USPAT	2004/03/16 14:52
-	86	73/862.454.ccls.	USPAT	2004/03/16 14:53
ļ -	31	(73/862.391.ccls. 73/862.451.ccls. 73/862.42.ccls. 73/862.381.ccls.	USPAT	2004/03/16 15:29
		73/158.ccls. 73/862.454.ccls.) and ((tension\$4 pull\$4 stretch\$4 draw\$4		
		stress\$4) near4 (deflect\$4 bend\$4 deformat\$4 force load\$4) near4 (wire		
		cable rope))		
-	304	73/\$6.ccls. and ((tension\$4 pull\$4 stretch\$4 draw\$4 stress\$4) near4	USPAT	2004/03/16 15:30
		(deflect\$4 bend\$4 deformat\$4 force load\$4) near4 (wire cable rope))		
-	33	73/862.46.ccls.	USPAT	2004/03/16 16:51